

*Laminator (soft plastic)*



*How to Laminate Round cable into Flat cable:*

- 1. Arrange the wire to flat type with correct pitch.*
- 2. Heat Shrink the Laminator (soft plastic) to cable.*
- 3. Crimp the wire with Laminator in to IDC connector*